

# Technical Data Sheet



Willamette Valley Company

www.wilvaco.com

800.333.9826

Partnering through  
service, innovation, and  
integrity

# FamoCrete

## Repair product for concrete

### DESCRIPTION

FamoCrete is a rigid, sag resistant polyurethane repair product for broken or spalled concrete. Easy to use, FamoCrete is supplied in ready-to-use universal cartridge. It is 100% solids and cures quickly to form a strong bond to concrete.

### WHERE TO USE

- **Walls**—fill voids or patch defects
- **Pillars**—repair damaged areas
- **Sidewalks**—transitions or spalls
- **Curbs**—broken or damaged areas

### FEATURES AND BENEFITS

- **Sag-Resistant**—ideal for vertical repairs
- **Trowelable**—easy to apply
- **Excellent Adhesion**—restore damaged areas
- **Fast Cure**—quick return-to-service

### PACKAGING

180ml Cartridge  
450ml Cartridge

### COLORS

Gray

### YIELD

180ml=14.4 lineal ft at 1/4" (4.32m at 6.3mm)  
450ml=36 lineal ft at 1/4" (10.8 m at 6.3mm)

### SHELF LIFE

1 year when properly stored.

### STORAGE

Store and ship this product in a clean, dry, low-humidity, shaded or covered environment at 60 to 90° F (15 to 32° C).

## TECHNICAL INFORMATION

### Typical Properties

<b>VOC</b> , lbs/gal (g/L), ASTM D 2369	0
<b>Set time</b> , seconds, 70° F (21°C)	120
<b>Tack-free time</b> , min., 70° F (21° C)	30
<b>Concrete adhesion</b> , psi (MPa), ASTM D 4541	500 (3.4) 100% substrate
<b>Hardness</b> , Shore A / D, ASTM D2240	92 / 50
<b>Viscosity</b> , cps, ASTM D 4878, mixed	16,000
<b>Service temperature</b> , ° F (° C)	-40 to 180 (-40 to 82)
<b>Compressive Strength</b> , psi, ASTM D 695	3,000

### Processing Parameters

<b>Application Method</b>	Caulk Gun
<b>Application temp</b> , ° F (° C)	50 to 90 (10 to 32)
<b>Recommended thickness</b> , in. (mm)	0.25 – 0.50 (0.63 – 1.25)

---

## APPLICATION

---

### SURFACE PREPARATION

#### CONCRETE:

1. The surface being repaired must be fully cured 28 days, structurally sound (200 psi or greater according to ASTM D 4541), clean (ASTM D 4258), and dry (less than 5%, ASTM D 4263).
2. Remove contaminants, dust, and other materials from surface. Concrete must be clean, dry, and sound prior to applying FamoCrete. Remove any contaminants before profiling surface.
3. Profile surface according to ICRI Guide 03732 to a minimum of CSP 3 by grinding, abrasive blasting, or hydroblasting.
4. Use compressed air to blow out loose debris, dirt and dust prior to applying FamoCrete.
5. For applying over cured FamoCrete, follow the above procedure.

#### PROCESSING

1. Always protect product from freezing. Precondition cartridge to 70°F (21°C) before dispensing material.
2. Wear protective gloves, cloths, and safety glasses while handling FamoCrete. Apply the repair material when the substrate temperature is stable and above 50°F (10°C).
3. Attach the supplied mixing tube to the top of the cartridge tube.
4. Dispense material by pumping caulking gun. DO NOT STOP FOR MORE THAN 1-MINUTE otherwise material will cure in mixing tube. Replace mixing tube if material cures in the mixing tube.
5. IMMEDIATELY trowel material to level and material. Thin and cold concrete surface applications can take up to 1-hour to cure.

6. Allow the material to cure for 12-hours at 70°F (21°C). Cure time will take longer at lower temperatures and when applied in a thin application.

#### APPLICATION

1. Apply the material with a trowel and level to surrounding surfaces. After product has become hard, a mechanical sander can be used to level or remove excess material.
2. FamoCrete will discolor or fade under UV light; however physical and performance properties will not be affected. Use aliphatic topcoat for color stability.
3. Material cure time will vary with temperature and thickness of material applied. Thicker applied product will cure faster compared to thin applications. Heat will also speed material cure.
4. Proper application is the responsibility of the user. Field visits by WVCO Representative are for the purpose of making technical recommendations only and not for supervising or providing quality control on the jobsite.

#### CLEANING & MAINTENANCE

- Use acetone or other available solvents to clean equipment.
- If there is any residual material left in the cartridge, leave the used mix tube in place, and store in an upright position. To use the remainder of the material in the cartridge, un-screw lock nut, and dispose of used mix tube. Attached new mix tube, and re-use lock nut, and follow application instructions listed above. .

---

## HEALTH AND SAFETY

---

Before handling, you should become familiar with the Material Safety Data Sheet (MSDS) regarding the risks and safe use of this product. To obtain an MSDS please call 800-333-9826 or send an email to: [msds@wilvaco.com](mailto:msds@wilvaco.com).

---

#### DISCLAIMER OF WARRANTY

TEST RESULTS ARE TO BE CONSIDERED AS REPRESENTATIVE OF CURRENT PRODUCTION AND SHOULD NOT BE TREATED AS SPECIFICATIONS. WHILE ALL THE INFORMATION PRESENTED IN THIS DOCUMENT IS BELIEVED TO BE RELIABLE AND TO REPRESENT THE BEST AVAILABLE DATA ON THESE PRODUCTS, NO GUARANTEE, WARRANTY, OR REPRESENTATION IS MADE, INTENDED, OR IMPLIED AS TO THE CORRECTNESS OR SUFFICIENCY OF ANY INFORMATION, OR AS TO THE SUITABILITY OF ANY CHEMICAL COMPOUNDS FOR ANY PARTICULAR USE, OR THAT ANY CHEMICAL COMPOUNDS OR USE THEREOF ARE NOT SUBJECT TO A CLAIM BY A THIRD PARTY FOR INFRINGEMENT OF ANY PATENT OR OTHER INTELLECTUAL PROPERTY RIGHT. EACH USER SHOULD CONDUCT A SUFFICIENT INVESTIGATION TO ESTABLISH THE SUITABILITY OF ANY PRODUCT FOR ITS INTENDED USE. PROPER APPLICATION IS THE RESPONSIBILITY OF THE USER. AS WITH ANY PRODUCT THE USE OF THIS PRODUCT IN A GIVEN APPLICATION MUST BE TESTED (INCLUDING BUT NOT LIMITED TO FIELD TESTING) IN ADVANCE BY THE USER TO DETERMINE SUITABILITY. TESTING IS THE REQUIREMENT OF BOTH ENGINEERS AND CONTRACTORS ALIKE. WVCO DOES NOT WARRANT THE APPLICATION UNDER ANY OR ALL CIRCUMSTANCES.

#### WILLAMETTE VALLEY COMPANY

[www.wilvaco.com](http://www.wilvaco.com)  
[info@wilvaco.com](mailto:info@wilvaco.com)

#### DIVISIONS

##### WESTERN DIVISION

1075 Arrowsmith Street  
PO Box 2280  
Eugene, OR 97402  
Tel 541.484.9621  
[www.POLYQUICK.com](http://www.POLYQUICK.com)  
[www.SPIKEFAST.com](http://www.SPIKEFAST.com)

##### EASTERN DIVISION

6662 Marbut Road  
Lithonia, GA 30058  
Tel 888.878.9826

##### MIDWEST DIVISION

1549 Hwy 2  
Two Harbors, MN 55616  
Tel 218.834.3922

##### PRECISION TECHNOLOGIES DIVISION

675 McKinley Street  
Eugene, OR 97402  
Tel 541.484.2368  
[www.pre-tec.com](http://www.pre-tec.com)

##### SOUTHERN DIVISION

100 Dixie Mae Drive  
PO Box 4450  
Pineville, Louisiana 71361  
Tel 318.640.5077

##### CANADIAN WILLAMETTE

19081- 27th Avenue  
Surrey BC V3S 5T1  
Tel. 800.663.4298

#### SUBSIDIARIES

##### ECLECTIC PRODUCTS INC.

Corporate Office  
1075 Arrowsmith Street  
Eugene, OR 97402  
Tel 541.284.4667  
[www.eclecticproducts.com](http://www.eclecticproducts.com)

##### IDAHO MILL & GRAIN

445 North 430 West Hwy  
PO Box 188  
Malad City, Idaho 83252  
Tel 208.766.2206

##### TAPEL WILLAMETTE LTD. S.A.

Av. Estero La Posada 3625  
Parque Industrial Coronel  
Coronel, Chile  
Tel 011.56.41.928.100  
[www.tapel.cl](http://www.tapel.cl)



W07-R&D-TDS-040

REV 00

Revision Date June 10 2016